	- N/	ednesday, 5/2/2007 3:44:00 P	DKA							=	
Date: User:		m Johnston	141		Droce	ess Sheet					
					FIUCE		4.4441.0/DE-01	IOLII DED II	ADMESS KI		
Custon		: CU-DAR001 Dar	rt Helicopters S	ervices		Drawing Name	: 4-MAN SIDE SH	HOULDER HA	AKINESS KI	1	
Job Nu		: 32137 r : 10413			4						
P.O. Nu	te Numbe ımber	r : 10413 : ねね	e e	ar en		Part Number	: D412702017				
This is:			6.0. No. : 20	A	•	Drawing Number	: N/A				
Prsht R		· NC		-		Project Number	: N/A				
First Is	sue		ype : MA	CHINED PA	RTS	Drawing Revision	: Coa				
Previou	ıs Run	NA				Material	- FIDIODA)	O4	2		Each
Written	Ву	:	Λ			Due Date	(: 5/9/2007	Qty:	2	Um:	Each
II .	ed & Appr	•	/	5,02			Ship				
Comme	ent	: Est Rev		New issue			U				
		Est Rev Est Rev		As per DSI 39351 07-03							
			7.C As per Ds		5-14 JLIVI			 			
Additio	nal Produ	ıct									
Job Nui	mber:										
Seq	. #:	Machine Or Ope	eration:			Description :					
	1.0	DC			DOCUME	NT CONTROL	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
											<u>5) —</u>
	Com	ment: DOCUMENT C				70	- 4		2 /	برك	ン
		Photocopy blue	efile and create	e labels per	PPP D412-7	702-017 CHG001	>cx	KS	07.05.	01	
	2.0	PACKAGING 1			PACKAGI	NG RESOURCE #1		o and marijuje.			
	Com	ment: PACKAGING F	RESOURCE#	1							
		Pick Packing K	it								
	3.0	D31963			Bar		. *				
						*					
	Com	•	Each(s)/Unit	Total:	2.0000 Ea	ch(s)					
		Pick: Packing k	Kit								
		Qty Part Number	er Des	scription E	3 2 /3	3/2					
		1 D3196-3	Bar								
	4.0	D31964	1811:1881		Bar						
			<u> </u>		2 2020 5-						
	Comi	•) Each(s)/Unit	Total :	2.0000 Ea	ch(s)					
		Pick: Packing K		intian [) atah						
		Qty Part Number 1 D3196-4	er Des Bar	scription E	3aton B <i>2996</i> 1						
	5.0	D3215041	Dai		Harness A	L					
	5.0	D3213041			Tiatiless A	.ssembly					
	Comi	ment: Qty.: 8.0000	Each(s)/Unit	Total :	16.0000 Ea			inniii arii inni			
İ	Com	Pick: Packing K	• •	TOLAI .	10,0000 Le	icii(s)					
		Qty Part Number		scription E	Ratch ₄			2			
		% D3215-041		s Assembly	L () A	160S			//>	52	
		9 80210 011	110111000	, 10001111017	7				1037	<u> </u>	

Page 1

Form: mrocess

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
7 1											
							-				
·											

Part No:	PAR #:	Fault Category:	NCI	R: Yes No	DQA: 🔁	Date: _<	A105109
	•			QA: N/C CI	osed:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
<u> </u>		Description of NC		Verification	A						
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
					-						

NOTE: Date & initial all entries

Wednesday, 5/2/2007 3:44:00 PM Date: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 4-MAN SIDE SHOULDER HARNESS KIT Job Number: 32137 Part Number: D412702017 Job Number: Seq. #: Machine Or Operation: Description: MS24694S152 Screw 6.0000 Each(s)/Unit Total : 12.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch MS24694-S152Screw MS24694S154 6.0000 Each(s)/Unit Total: 12.0000 Each(s) Comment: Qty.: **SCREW** Batch: HOOK AND LOOP TIE 8.0 D355111 8.0000 Each(s) Comment: Qty.: 4.0000 Each(s)/Unit Total: HOOK AND LOOP TIE BATCH: INSPECT 100% KITS FOR COMPLETED QC4 9.0 Comment: INSPECT 100% KITS FOR COMPLETENESS 10.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412 Location: QC21 11.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No);	PAR #: Fault Category:	NCR: Yes	No DC	A:	Date: _	
			QA:	N/C Close	ed:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Verification	A 1	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
							·				
		•									

NOTE: Date & initial all entries